

25X1

TOP SECRET

HANDLE VIA

CONTROL SYSTEM

[ ] NATIONAL RECONNAISSANCE OFFICE  
WASHINGTON, D.C.

OFFICE OF THE DIRECTOR

March 20, 1970

MEMORANDUM FOR Assistant to the President for National  
Security Affairs  
Attorney General  
Deputy Secretary of Defense  
Under Secretary of State (Political Affairs)  
Director of Central Intelligence  
Executive Secretary, 40 Committee

SUBJECT: TAGBOARD Missions

Following is a brief summary of the November 10, 1969  
operational mission and the February 20, 1970 test mission.  
A summary of all flights to date is attached.

TAGBOARD flew its first limited operational mission  
over South China on November 10, 1969. Launch and early  
flight were successful as the drone obtained the programmed  
altitude of 84,000 feet and a cruise mach of 3.27. During  
the terminal phase of the flight the drone was not acquired  
(visually or electronically) and the payload was not recovered.

NSA reported no SIGINT that could be correlated with  
the mission. The drone's position was fixed at only 50 miles  
off the Island of Hainan and 80 miles from the China mainland,  
just prior to the drone's telemetry being turned off on the  
inbound track well within range of coastal air defense radars.  
The drone's operating altitude, speed and small radar cross  
section (.2 sq meter frontal area with a 15° depression  
angle) give it a high probability of survival.

Investigations and laboratory simulations now indicate  
that computational errors in the drone's inertial navigation  
system (INS) prevented the drone from flying the programmed

25X1

25X1

MORI/CDF

NRO review(s) completed.

25X1

25X1

TOP SECRET

CONTROL NO. [ ]  
COPY 1d OF 1 COPIES  
PAGE 1 OF 5 PAGES

**TOP SECRET**

route. Self destruction probably occurred after fuel exhaustion upon descent at the pre-set altitude of [REDACTED] Software changes have since been made and tested to correct the computational errors, and a "fail safe" feature has been incorporated in the INS that will provide positive control of the drone's flight path. *25X1*

On February 20, 1970, TAGBOARD flew a completely successful test mission to validate the software and "fail safe" changes to the INS program. [REDACTED] *25X1*

The TAGBOARD system is now ready for another operational test mission. Drones are located at Beale AFB and are ready for flight.

1 Attachment  
Summary of Flights

25X1

ILLEGIB

**TOP SECRET**

**TOP SECRET**

25X1

25X1

SUMMARY OF TAGBOARD B-52 LAUNCHES

November 6, 1967. Drone #507. PMR. (PACIFIC MISSILE RANGE)

Launch and boost were successful. Drone attained a mach [redacted] Cruise flight was not sustained due to low inlet recovery; deformed inlet cone primary suspect. Drone travelled 134 miles down range and the hatch was not recovered.

December 2, 1967. Drone #509. PMR.

25X1

Launch and boost were successful. Free flight continued on course for [redacted] feet less than normal). Flight terminated prematurely after failure of the hydraulic system and subsequent loss of control. The hatch was not recovered.

January 19, 1968. Drone #508. PMR.

Launch and boost were successful. The drone travelled 550 miles down range, then the flight terminated prematurely when the drone began a pitch down and roll to the left. Telemetry was lost. Most probable cause of failure was electrical malfunction. The hatch was not recovered.

April 30, 1968. Drone #511. PMR.

Launch and boost were successful. Following booster ejection, the drone was unable to sustain cruise and lost altitude and speed due to low thrust from the engine (inlet not started). Drone travelled 150 miles down range and was destroyed. Hatch not recovered.

25X1

June 16, 1968. Drone #512. PMR.

Successful test flight. [redacted]

25X1

The hatch was air-recovered by JC-130 aircraft.

**TOP SECRET**

CONTROL NO. 1d OF 1 COPIES

**TOP SECRET**

July 1, 1968. Drone #514. PMR.

During pushover at the top of boost phase, the drone became laterally unstable due to insufficient autopilot gains. At separation, the booster struck the drone, rupturing the drone's fuel tank. The hatch ejected upon command and was recovered from the water in good condition.

August 28, 1968. Drone #516. PMR.

Launch and boost were successful. However, the drone's engine remained at minimum power and cruise altitude was not maintained. The hatch ejected at an excessive speed on descent and was not recovered.

25X1

December 15, 1968. Drone #515. PMR.

Successful test flight.

This was the first mission to test the total system with the camera aboard. The hatch was air-recovered by JC-130.

February 11, 1969. Drone #518. PMR.

Launch and boost successful. Apparent shift in autopilot control at excessive mach caused the drone to descend resulting in the inlet remaining only partially started with attendant loss in thrust. Severe oscillations resulted. Drone believed to have structurally destroyed itself. Hatch was not recovered.

25X1

May 10, 1969. Drone #519. PMR.

Successful test flight.

Hatch was air recovered by JC-130.

July 10, 1969. Drone #520. PMR.

Successful test flight.

Hatch was air-recovered by JC-130.

25X1

**TOP SECRET**

CONTROL NO.

**TOP SECRET**



November 10, 1969. Drone #517. First operational mission.

Launch and boost successful. Computational errors in the drone's Inertial Navigation System prevented drone from flying the programmed route. Self-destruct believed to have occurred upon descent at [redacted] feet. Hatch was not recovered.

25X1

February 20, 1970. Drone #521. PMR.

Successful test flight. [redacted]

[redacted] Changes to INS program validated.  
Hatch was air-recovered by JC-130.

25X1

25X1



**TOP SECRET**